

CITY OF SAN ANTONIO
San Antonio Fire Department
MEMORANDUM

TO: SAFD and DSD Associates
FROM: Asst. Chief Earl Crayton II, Fire Marshal
DATE: March 10, 2008
FILE: Code Interpretation Manual

INTERPRETATION NUMBER: CI2008-003

TITLE: Standpipe System Hose Connection Locations

CODE EDITION: 2006 International Fire Code (IFC)

SECTION: 905.4

PURPOSE: To clarify the required location for Class I standpipe system hose connections in required stairways.

QUESTION: When installed in required stairways per 2006 IFC Section 905.4, is it acceptable to locate Class I standpipe system hose connections at the floor level landings rather than the intermediate floor level landings?

ANSWER: No. When installed in required stairways per 2006 IFC Section 905.4, Class I standpipe system hose connections are required to be located at the intermediate floor level landings between floors. San Antonio Fire Department does not allow the hose connections to be located at the floor level landings in lieu of the intermediate floor level landings for these standpipe hose connections.



Asst. Chief Earl Crayton II
Fire Marshal
San Antonio Fire Department